

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-013525**Date Inspected:** 05-Apr-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhao Chen Sun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

Tower Trial Assembly

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW):

Weld joint # 03A located on West Tower Lift-1 Shear Plate at B/C corner outside WSD1 – A423A/H. Welder is identified as 040723. ZPMC Quality Control (QC) Inspector is identified as Zhu Yuan Yuan. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2233 – Tc – U5 – F.

Weld joint # 006 located on North Tower Lift-1 Bearing stiffener Plate WSD1 – SA295B/E. Welder is identified as 205649. ZPMC Quality Control (QC) Inspector is identified as Wang Cuang Xin. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2333 – Tc – P4 – F.

(See attached photo)


Weld joint # 03A located on South Tower Lift-1 Shear Plate at B/C corner outside SSD1 – A111A/H. Welder is identified as 053316. ZPMC Quality Control (QC) Inspector is identified as Zhu Yuan Yuan. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2233 – Tc – U5 – F.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Weld joint # 001 located on North Tower Lift-1 Bearing stiffener Plate WSD1 – SA279. Welder is identified as 040736. ZPMC Quality Control (QC) Inspector is identified as Wang Cuang Xin. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2333 – Tc – P4 – F.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest - 15000422360, who represents the Office of Structural Materials for your project.

Inspected By: Kumar,Sandeep

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer